

BENCH ELECTRIC ELECTRODE TIP DRESSER



Dressing of Caps / Electrodes:

some of the contract.

Insert used cap or electrode on Taper Shank or Taper Socket.

- Push Lever to insert cap tip into Electric Dresser.
- Electric Motor will start automatically.
- Cap / Electrode will be dressed in 2/3 seconds.
- Push lever to full right, electrode will be ejected automatically and fall in blue bin.
- Cutters can be supplied to suit the shape of electrodes.
- Cutters can be replaced / changed in 30 seconds.

